



Reference Marks				
Mammoth Mine Grid				
Point Id	Easting	Northing	RL	Description
Conc3	28495.944	21966.089	251.648	Pillar
21/J	27799.262	21069.815	314.735	Pillar
STN 104	27559.61	21276.19	280.30	Iron pin



REVISIONS		The Surface Drains well and there are no areas of pooling	M.H. LODEWYK CONSULTING SURVEYOR MOUNT ISA PH-07 47434155 FAX-07 47434710 6 SECOND AVENUE EMAIL survey@lodewyk.com.au	LEVEL DATUM A.H.D.		CLIENT Birla Mount Gordon	
				DATE SURVEYED 29 August 2014		Survey of Old Tailings Dam	
				SURVEYOR D.I. ATKINSON		PASSED	DATE
				SCALE 1:750 (A1)			
							10.018.150v2